

The altimeter setting procedures in use are generally conform to those contained in ICAO
 Altitudes are rounded to 1000 feet above as prescribed in DOC 8168 - OPS 611

Table of altitudes and Transition Levels for Moroccan Airports

Transition Levels for local QNH values in HPA

Airports	ICAO CODES	Transition Altitudes	Transition Levels for local QNH values in HPA			
			<977	from 977 to 994.9	from 995 to 1013.1	>= 1013.2
AGADIR	GMAD	5000	75	70	65	60
AL HOCEMA	GMTA	6000	85	80	75	70
BENSLIMANE	GMMB	4000	65	60	55	50
BOUARFA	GMFB	8000	105	100	95	90
CASABLANCA	GMMN	4000	60	55	50	45
DAKHLA	GMMH	3000	55	50	45	40
ERRACHIDIA	GMFK	6000	85	80	75	70
ESSAOUIRA	GMMI	3000	55	50	45	40
FES	GMFF	7000	95	90	85	80
GUELMINE	GMFF	6000	85	80	75	70
IFRANE	GMFI	Nil				
LAAYOUNE	GMLL	3000	55	50	45	40
MARRAKECH	GMMX	4000	65	60	55	50
NADOR	GMMW	5000	75	70	65	60
OUJDA ANGADS	GMFO	6000	85	80	75	70
QUARZARATE	GMMZ	8000	105	100	95	90
TANGER	GMTT	5000	75	70	65	60
TAN TAN	GMAT	3000	55	50	45	40
TETOUAN - SANIAT	GMTN	6000	85	80	75	70
ZAGORA	GMAZ	Nil				

FOR SIMULATION PURPOSES ONLY - IVAO MA by Amilcare Pulicani